NOTE: revised 2/84 MARYLAND GEOLOGICAL SURVEY Merryman Hall The Johns Hopkins University Baltimore, Maryland 21218 (301) 338-7156

Congressional Districts 2 / 19 ED 5 / Hopewell Twp. COUNTIES (MD/PA) HARFORD / YORK M&D milestone no. 40(43) MHT-HSI no. HA-1015 (entered c. 1970) 1310153227 MAGI no. PROTECTED/ENDANGERED/MISSING from site

FIELD SHEET: MASON & DIXON LINE, MARYLAND-PENNSYLVANIA BOUNDARY MARKER SURVEY

LOCATION: USGS 7.5'quadrangle/date Norrisville 1957/74UTM 18.36770.439768 oriver site/moved/date 1902 bench mark/date none At northwest corner of junction of PA Al998 with MD 23, Wiley, MD-PA. Unexposed base in concrete foundation only: / about I' from road edge, flanked on north by 4 wood posts & utility pole #114-1, standing guard but not protecting. Can be easily seen all seasons except when covered by snow.

DIRECTIONS TO SITE:

From M&D 39(41): retrace New Park Road about 0.3 mile north to junction of road to Wiley (PA A2450); turn left (west) & follow this + A1998 about 1.2 miles to its end + at the bend in MD 23 and monument site. Park at store just north (west side of road) DESCRIPTION/MEASUREMENTS: original/werkica/replacement/date 1767 below ground base and concrete foundation (1902), in place at relocated site, unprotected but visible foundation (1902), in place at relocated site, unprotected but visible 12" wide x 14" high; Penn shield discernible but very weathered; big shallowichip ents shield at bottom; bits of margin remain; chips 114" wide x 14" high; most fluting and some margins remain; face very E face: MONUMENT weathered; chips along all edges

S face (MD):

| 12" wide x 14" high; Calvert shield barely discernible; entire face
| very weathered and nicked; chips along all edges
| 11%" wide x 14" high; no fluting or margins remain; face very weathered;
| chips along all edges
| top: | rises about 2" as low pyramid to centered apex (now with pit); planes
| discernible; huge chips | top of top northeast & southeast corners
| bench mark: | none indicated on maps; none on/monument in museum S face (MD): W face:

top:

CONDITION OF MARKER/FOUNDATION: excellent/good/fair/deteriorated/ruins/unexposed 1900-03 Resurvey notes (order no.43), as in MGS Vol. 7, 1908, p.43

43. A "crown stone" brought from Washington County, Md., and placed a short distance to the westward of the preceding monument, in the intersection of the two roads mentioned. It is situated in the grassy triangle between the

1950 Inspection notes (present order no.43, photo no.40) as in Bayliff, 1959, Appendix C, p. 98

43.\* Top removed on Halloween 1956. Now lost.

1979-82 Inspection notes: order no. 40 (43); photos/negatives/slides no. 40 (43) 40(43). Original M&D 1767 crownstone replacement from Washington County/set 1902 in relocated site; broken off at ground level about 1946 (T. H. Slaughter report 9/8/48); reset by 4/10/49 (dated Trussell photos); "removed on SURROUNDING PROPERTY OWNERS (MD/PA): names, addresses, phones tax map , block , P. , deed

tax map AL, block , P.17A , deed 60Y / 291, acres Maurice H. & Helen I. Williams, RD 1, Stewartstown, PA 17363

Phone: 717/993-2642

RECORDED BY: names, addresses, phones, dates Alice Martin 2/10/80, 2/21/80, 2/2/84 14308 Mount Avenue, Phoenix, Maryland 21131 Phone: 301/472-2128 Assisted by Clyde Martin 2/10/80 & 2/2/84; Jean Ewing 2/21/80

Also see: reverse side X , B&W photos X , negatives X , color slides X , maps X , MHT-HSI form , other X

# CONDITION OF MARKER/FOUNDATION, continued

1979-82 Inspection notes:

Halloween 1956. Now lost." (1950 Inspection addends in Bayliff 1959). Missing top identified by A. Martin 2/2/84 through matching of Trussell photos as monument now installed in collection of the Historical Society of York County, 250 East Market Street, York, Pennsylvania. Top is in fairly good condition, attractively displayed. Base and foundation are in place at relocated site but unprotected.

## NOTES

We recommend: further research as to the record of the break and disappearance of the top of this monument; alerting the surrounding property owners (including appropriate road maintenance officials) for the need to protect the remaining stone base and concrete foundation until MD and PA plans can be made to raise or reestablish a monument there or elsewhere nearby; and, if the original top or a new top is planned, to reconsider utilizing the original/base (still believed in place/in the Wiley field) east of the road, No. 40(42), since the present site is so unsatisfactory with regard to traffic and road maintenance machinery.

From the Trussell photos, the replacement crownstone, No. 40(43) appears to have been cemented to its base at grade level and the concrete foundation built up to slightly above the mended break. The indentation we found seems to confirm this. If so, the crownstone could have been rather easily broken off and/or removed, being only about 12" square by about 1½ above ground; so some other, more substantial repair needs to be utilized for such breaks. We also urge that some policy decision be made concerning the demise of the two stone bases: No. 40(43) is probably about 3' at least into the ground and surrounded by a collar of concrete when set in 1902; No. 40(42) may not be as much or more than 12" into the ground, and with no collar or other foundation. We hope MD and PA will consider allowing the Historical Society of York County to retain the top and be given one of the two original bases at the 40(42) or 40(43) site, if some suitable arrangement can be made/for a substitute.

# B&W PHOTOS/NEGATIVES

5x7 NW corner of base & foundation (neg #20), Jean Ewing 2/21/80

5x7 SE corner of base & foundation (neg #16), "

5x7 View SE showing setting/MD 23 (neg #17), "

3½x5 View NW showing setting/MD 23/George Comer house (1980.6.32), Alice Martin 2/21/80

# COLOR SLIDES

2x2 NW corner of base & foundation (neg #12), Jean Ewing 2/21/80

2x2 SE corner of base & foundation (1980.5.28), Alice Martin 2/21/80

2x2 View NW of setting & George Comer house (1980.5.26), "

2x2 View NE of setting & Wiley farm (1980.5.24), Alice Martin 2/10/80


#### MAPS

USGS 7½' topographic quadrangle section 1900-03 Resurvey engineer's map (Plate XVIII), updated MD tax map section MGS topographic map of Harford County

## OTHER


7 pages of xerox: 5 of earlier views (B&W contact photos from MHS Trussell collection 5/30/48 & 4/10/49), B&W photos from MHS Harwood collection undated (c. 1930's) & 11/15/31; 2 of T. H. Slaughter observations 9/8/48 (MGS file)

(MGS file)
6 duplicate 18:40, 3 archers (PP2.5, 16., 3a + PP2.73. 2a, 4a, 5a, 6a



(charan

0



MITT-HSI: HA-1015




TEXT! HASIN EDIXON LINE | 40TH HILE STONE |
HARVLAND - PENNSYLVANIA BOUNDARY LINE |
SURVEYED E HARKED | 763-68 BY TWO | ENGLISH
ASTRONDHERS CHARLES HASEN E JEDETHAM
MIXEN THIS IS ENE OF THE ! CROWN "STONES SET
EVERY FIVE MILES | DISPLAYING THE COAT OF ARMS
OF LORD | BALTIMORE ON SOUTH & THE PENNS ON |
STONES, WITH MERITAGE HILE STANKED BY
STONES | ITTERNEDIATE HILE STANKED BY
STONES | ITTERNED FRING HARVAND & P PENNS YVANIA




MED NO. 40

c, early 1/30's ?

from MHS coll: 50088 (HARWEED COLL)






No to CORIO, FROM WASHING TON CO.)

Int wood before

PHOTO: ART VIEW CO, HUGH GWYNN 11/15/31 11HS (ACCESSION) 50088) 1 ACCESSION 50088)







PHOTO: ART VIEW CO. HULL GOVEN 11/15/31
MHS (ACCESSION 50088) ARWEND COLL, 11/15/31





SE CORNER PHOTO: DR.A.L. TRUSSELL 5/30/48 BEFORE RESETTING



MED LINE;

40 (43)

1766

REPLACEMENT

FREST WASH'N TON CO. BY

1980-03 RESURVEY, NEW LOCATICAL ON THE

A RESETTIAL

N/S PHOTO: DR A. L. TRUSELL 5/30/48





PHOTO: DR. A. L. TRUSSELL 4/10/49



PHOTO: DR A.L. TRUSSELL 4/10/49

or m by " Lection

NS



... ESTIGATION OF MASON WED DIXON LINE MARRON CO. /YORKCO.

DATE: SEPT. 8. 1948

LOCALITY: WILEY. MD. AND PA. ON- MD. POUTE. 23- HARFORD-YORM
COUNTIES-

INVESTIGATOR! T. H. SLAUGHTER GRE?

# 035EPLATIONS!

CONCRETE BASE 15;

CONCRETE BASE 15;

MARKET S'E

CONCRETE BASE-2 MELSI:

MD: POURE

S. D.

S. D.

S. D.

F. D.

F

2- THE SIZE OF THE MARKER. IS. APPROXIMATELY.

1' L" SQUARE AND. I', 4" HIGH. WITH THE TOP.


SHAPED IN A LOW PYRAMIDAL MANNER- THE TOP HAD

A SMALL CONCAUE DEPRESSION OF ABOUT 2"DIAMETER,

3, THE, CINCRETE BASE IS APPROXIMATELY, 2'-8"

SQUARE, AND IS FLUSH WITH THE GROUND LEVEL.

4, THE COMPISITION OF THE STONE MARKER IS.



- LIMESTONE, IT IS NEWY FOSSILIE EROUS AND LEENTHERS.

  A SLIGHT EREYISH. IN WITE, AND IS SLIGHTLY CHALRY

  IN. COMPOSITION:
  - S- THE ONLY VISIBLE SIGNS IF INSCRIPTIONS

    ARE TWO INDISTINOT INSIGNAS OF ARMS ON

    OPPOSITE SIDES.
  - 6. THE STINE MARMER WAS BOOKEN OFF FLUSH.
    WITH THE TOP GROUND LENEL LEXUNG A NOT TOO


    JAGGED BOTTOM SUMFACE,
  - 7- THE MARITER WAS BRITTEN DUE TO AN AUTOMOBILE ACCIDENT AT LEAST. 2 YEARS AGO.
  - DOWN AT THE TIME OF THE ACCIDENT AND


    SUBSEQUENTLY HAS BEEN CARRIED AWAY.
    - 9. AS- SHOWN IN THE DIAGRAM. (IST PARAGRAPH)

      THE S.E. CORNER OF THE CONCRETE BASE IS:

      3 1/2 FEET AND 5 FEET. DISTANT FROM THE.

      ROAD.






CROWNSTONE (1767) BROUGHT FREM WASHINGEN COUNT, NW CORDER OF JUNCTION OF A-1998 WITH HD-23, WILEY, 450VE-GROUND PORTION OF AN ORIGINAL MASON EDINON I USED AS A REPLACEMENT AT RELOCATED SITE MISSING FROM SITE SINCE ABOUT 1956.

JPEN WAT OF AKK NE CORNER (

YORK, PA

GAFT TO HES FROM HISTORICAL

こち、丁文宣传



7 DESCRIPTION

EXCELLENT

\_\_FAIR

L\_6000 (top)

CONDITION

\_\_DETERIORATED

\_\_RUINS XUNEXPOSED (base) CHECK ONE

\_ALTERED

LUNALTERED (top)

CHECK ONE

ORIGINAL SITE


X MORNO DATE 1902 (new site)

### DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

Milestone No. 40 (43) was an original Mason and Dixon crownstone of 1767 brought from Washington County/to replace the crownstone originally set in the vicinity to mark the 40th horizontal mile west of the initial stone at the northeast corner of Maryland, the beginning point of the 230.228-mile West Line. Although the site of the original/is now unexposed and the aboveground portion broken off and removed before the 1900-03 Resurvey of the Maryland-Pennsylvania boundary, the present site was established at a more suitable location, an estimated 115' more or less, west of the original, on the Line. The above ground portion is now in the collection of the Historical Society of York County, Pennsylvania; but the below-ground portion is still in place, firmly imbedded in the collar of concrete surrounding it at the time it was set. The condition of the base is unknown; but the condition of the top is fairly good, and makes a handsome, important addition to the Society's /colonial exhibit.

Wiley is a little crossroads cluster of farmhouses and a store. here is quite flat and the farms and other houses are scattered. This new 1902 site is in the northwest corner formed by the junction of PA A-1998 with MD 23 at its right-angle bend, in Wiley, about l' from the road edge, flanked on the north by 4 wood posts and a utility pole (#ii4-1), all standing guard but none protecting. This grade-level patch of concrete with its squared indentation where the top was reset by the time of 4/10/49, can be seen easily from the roads, all seasons (except when covered by snow).

The monument top stood in place from 1902 until about 1946, when it was broken off at ground level (T. H. Slaughter report 9/8/48 on file at Maryland Geological Survey); it was reset apparently just by cementing, by the time of the Trussell photos of 4/10/49 (FHS-PP2 collection); only to have been "removed on Halloween 1956" (Bayliff, 1959, p. 98). The Eistorical Society of York County does not have any accession records for this morument; but has mounted this top appropriately and without any alteration. Originally, it was an embellished oclitic limestone post with a low pyramidal top, quarried and carved in England, measuring about 12" square by about 412' long, cut to stand about 3' above ground. It now measures approximately 12" square, by about 14" high plus an additional rise of the top of about 2" to a centered apex. Both the Penn and Calvert shields are discernible but very weathered, as are all surfaces. CONTINUE ON SEPARATE SHEET IF NECESSARY Most fluting remains on the east side but not the west, and there is a large chunk out of the top northeast corner.





MAT-431 - 414-1015 1165 Mason Dixon west line stone 40 NIW CORRER (OF STONE BASE & FOUNDATION) AT GRADE LEVEL Not original correct location. Site o relocated stone



MASON EDIXON WEST LINE:

THE STONE NO. 40 (SITE)

LOCKING NW TOWARD STONE

E GEORGE COHER HOUSE

11A-1015

1147-HJ1:

PHOTO: ALICE MARTIN 2/21/80 (1980.632)






1747-ASI: HA- 1015 1965 Mason Dixon wist line stone to BROKEN OF FELEN NUMBER PESED Site of relocated stone. Not original correct location



MHT-NS1! HA-1815 1.6 Mason Dixon west line stone 40 Not original site. This is site of relocated stone.



PA 84.5

AN ONIGINAL (ROWNSTONE REPLACEMENT (1767)
AT RELOCATION (1902)
NOW IN COLONIAL COLLECTION INSTALLED AT

THIS ITEM MAY NOT BE REPRODUCED
WITHOUT PERMISSION FROM THE
HISTORICAL SOCIETY OF YORK CO.
250 EAST MARKET ST.

YORK, PA. 17403

NE CORNER (- / PENN COAT OF ARMS)

PHOTO:

2/2/84

GIFT TO MGS 3/20/84

Photo: Historical Society of York County 2/81


Above-ground portion of an original Mason and Dixon crownstone (1767) brought from Washington County and used as a replacement at relocated site (1902), northwest corner of junction of PA A-1998 with MD-23, Wiley, MD-PA (Harford/York counties), Norrisville quadrangle.

Missing from site since about 1956.

Now installed in permanent colonial exhibit at the Historical Society of York County, 250 East Market Street, York, PA 17403.

View of northeast corner (--/Penn coat of arms)

Negative on file at Historical Society of York County; print a gift from the Society to Marylani Geological Survey.





MAS TRUSSELL COLL. PP2.73.5 a Duplicate contact print deaccesseemed 6/83 as gif

MED WEST LINE: HILESTONE 40(43) REPLACEMENT CROWNSTINE OF 1767 + RELOCATION (1902)

DRITHUSSELL & SIS (CALVERT

PHOTO: ?? (EISIE MARSDEN, partably)



MHS TRUSSELL CULL. PP2,73,2a

PHOTO: JO AL TRUSSEU 5/3/148

PHOTO: DR AL. TRUSSELL 5/30/48

DiPLICATE CONTACT PRILT DEACCE STRUED 6/83 AS GIFT TO HOS ANCHIVES



40 to have Stone Man & Down 4557 Line REPERCENTURE CHARLYSTAUF SET DEACCESSIONED TOTALS BY HAD FROM PROT HARMSONCELL AS 61FT TO HISS



MED WEST LINE: MILESTONE 40(43)

RELOCATED REPLACEMENT
(ONE-1767 CROWNS LAG)

N/S (Plan coat of a som)

PHOTO: DR. A.L. TRUSSELL 4/30/48 de accessored 6/83 for 1105 auchives



MHS TRUSSELL CLLL. PP2.73.40 Duplicate contact prient deaccessioned 6/83 as geft to 1165

MED WEST LINE: MINESTRATE 40(43) REPLACEMENT CROWESTER & DF1767 + RELOCATION (1902) SIS (CALVERT CEAT OF ARTS)

PHOTO: DR.A.L. TRUSSELL 5/30/4/8



MHS TRUSSELL COLL. PP2.73.60 Duplicate contact print deaccessioned MED WEST LINE: MILESTENE 40 (43)
REPLACEMENT CROWNSTONE OF 1767 + RELICATION (1902) DR. TRUSSELL ESE CORNER (CALVERT CLATOFARMS/-) PHOTO: ?? 5/30/48
(ELSIE MAKSDER, probably)



(duplicate) PP2.5.16

MED WEST LIVE: MILES CIE 40 (43)

RELUCATED REPLACEMENT

(LATE, 1767 CROWNSTONE)

SE COUNCY

(Calvert coat farm /-)

PHCTO: IR.A.I. TRUSSEIL 5/30/48 deach second 6/83 from 1145 Trussell coll. for MHI a chives